

Work Order ID 88047

88047

Page 1

Wednesday, July 25, 2012 2:33:03 PM

Item ID: D4148-041 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Crosstube Lug Assembly, Fwd
 Start Date: 7/24/2012 Start Qty: 2.00 *2* Cust Item ID:
 Required Date: 7/25/2012 Req'd Qty: 2.00 *2* Customer: CU-DAR001
 Reference: RMA RA111369 - RETURN

Approvals: Process Plan: MVF Date: 12-07-25 Tooling: _____ Date: _____ Run Start *NR1*
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D4148	D								

100 0.00

100

QC Memo 0.00
 Quality Control INSPECT RA 111369 D4148-0410 X 2 B60894

KITS ARE SCRAP

GIVE TO SMALL FAB TO SCRAP

110 QC21- Final Inspection - Work Order Release 0.00

110

QC Memo 0.00
 Quality Control

~~DAS~~

DAS
10

12/14/12

12/17/30

Picklist Print

Wednesday, July 25, 2012 2:33:03 PM

Page 1

Work Order ID: 88047

Parent Item: D4148-041

Parent Item Name: Crosstube Lug Assembly, Fwd

Start Date: 7/24/2012

Required Date: 7/25/2012

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP Rev:A 10.06.24 new issue DD verf:EC
IPP Rev:B 10.07.22 as per revB DD verf:JLM
DD verf:EC
IPP Rev:C 10.10.29 as per revC
IPP REV:D 11.03.02 AS PER DWG REV.D DD VERF:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4148-041 Crosstube Lug Assembly, Fwd		Manufactured	No				Each	14.0000		2			

Location

Loc Qty

Loc Code

ST468

14

85752

14

I X 60894 MF 12-07-25

U 12-07-30

RA111369 D4148-041

B60894

Received @ Dart July 3rd, 2012
Inspected @ Dart July 6th, 2012

Customer: TRANS AERO HELICOPTERS
Customer Contact: DENNIS PEDERSON
Shipped from: CHEYENNE WY USA

Instructions for RA 111369 D4148-041 B60894

- SCRAP now at rev D
- Needs new work order to scrap

Time Estimate = 1 HOUR ONLY (QC)

Departments Required: QC to scrap

Pictures Attached = NO

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**